



Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

Amendment 39-1689; AD **73-15-04**

AVCO LYCOMING Model HIO-360-D1A Engines

PDF Copy (If Available):

▼ Preamble Information

DATES: Effective July 23, 1973.

▼ Regulatory Information

73-15-04 AVCO LYCOMING: Amdt. 39-1689. Applies to HIO-360-D1A model engines installed on Hughes Models 269C and 300C helicopters.

Compliance required within 300 hours time in service after the effective date of this AD and every 300 hours in service thereafter.

To prevent possible failures of the Bendix part numbers 10-349235-3 and 10-349235-4 magnetos,

replace the part number 10-391315 rubber drive plate grommet in accordance with Lycoming Service Bulletin No. 364 or equivalent procedure approved by Chief, Engineering and Manufacturing Branch, FAA, Eastern Region.

This amendment is effective July 23, 1973.

▼ **Footer Information**

▼ **Comments**