

652 Oliver Street Williamsport, PA 17701 U.S.A. 570/323-6181



January 18, 1996

Supplement No. 1

To

Service Bulletin No. 524

On the **ATTACHMENT** for **LIST II** to Service Bulletin No. 524 the serial numbers for the following engine models should read:

O-290 series engines with serial numbers up to and including L-8559-21.

*O-360, HO-360 series engines with serial numbers up to and including L-15276-36A, L-23385-36A thru L-31007-36A inclusive except for the following: L-30988-36A, L-30989-36A, L-30990-36A, L-30991-36A, L-31001-36A, L-31002-36A, L-31003-36A.

HIO-360-D1A, -E1AD, -E1BD, -F1AD series engines with serial numbers up to and including L-22579-51A except for the following: L-22311-51A thru L-22313-51A, L-22396-51A, L-22397-31A, L-22416-51A, L-22546-51A thru L-22549-51A, L-22563-51A, L-22568-51A thru L-22571-51A inclusive.

LIO-360 series engines with serial numbers up to and including L-100-67A, L-1076-67A thru L-1113-67A inclusive.